

Type of airbag inflator	Time by which recall action must be initiated	Time by which inflators of this type must be replaced
Alpha Inflators	Subaru vehicles are not fitted with Alpha Inflators.	
All other Affected Takata Airbag Inflators	As soon as practicable after the ACCC notifies a Supplier of approval or prescription of a Supplier's Communication and Engagement Plan under section 7(4) of the Consumer Goods (Motor Vehicles With Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018 and on a rolling basis to allow for completion of replacement by the required dates.	As soon as practicable, and in any event by 31 December 2020 unless otherwise approved by the ACCC, with replacement prioritised according to the Priority Factors in clause 4 of Schedule 1 of the Consumer Goods (Motor Vehicles With Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018 and the applicable Quarterly Completion Schedule.

Subaru (Aust) Pty Limited
Recall and Replacement Timetable
Version 1, 02/07/2018

Subaru (Aust) Pty Limited ABN 95 000 312 792

4 Burbank Place Baukham Hills NSW 2153

PO Box 8311 Baukham Hills NSW 2153

T +61 1300 550 994 | F +61 2 8892 9131

subaru.com.au/takata-recall